PRODUCT DISCONTINUATION

PD_098_08

Reason: portfolio adjustment

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
PBL38620/2SHA	SP000007870	P-/PG-SSOP-24	FlexiSlic^{TM}	PBL38621/2SHA	SP000007871	PG-SSOP-24	FlexiSLIC^{TM}
PEB 2266 H V2.2	SP000007518 SP000007519 SP000007520 SP000213766	PG-MQFP-64 P-/PG-MQFP-64 P-/PG-MQFP-64 P-MQFP-64	Sicofi^{TM}-2µC	PEB 2466 H V2.2	SP000007515 SP000007516 SP000007517	PG-MQFP-64	Sicofi^{TM}-4µC
PEB 4164 T V2.3 GD	SP000007419	P-/PG-DSO-20	AHV-SLIC-P	no replacement			

■ Last order:	2009-02-28
■ Last delivery:	2009-08-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!