

# PRODUCT DISCONTINUATION



## PD\_074\_06

Reason: Manufacturing at Munich Perlach will be phased out.

| DISCONTINUED |                                   |                    |         | NEW (REPLACEMENT) |                  |          |         |
|--------------|-----------------------------------|--------------------|---------|-------------------|------------------|----------|---------|
| Device       | Ordering Code *)                  | Function           | Package | Device            | Ordering Code *) | Function | Package |
| KT210        | <b>SP000011509</b><br>Q62705K 334 | Temperature Sensor | TO92    | none              |                  |          |         |
| KT230        | <b>SP000011513</b><br>Q62705K 335 |                    | SOT23   |                   |                  |          |         |
| KT230 E6393  | <b>SP000011514</b><br>Q62705K 443 |                    | SOT23   |                   |                  |          |         |
| KTY23-5      | <b>SP000011510</b><br>Q62705K 262 |                    | SOT23   |                   |                  |          |         |
| KTY23-6      | <b>SP000011511</b><br>Q62705K 263 |                    | SOT23   |                   |                  |          |         |
| KTY23-7      | <b>SP000011512</b><br>Q62705K 264 |                    | SOT23   |                   |                  |          |         |
| KTY21-5      | <b>SP000011506</b><br>Q62705K 258 |                    | TO92    |                   |                  |          |         |
| KTY21-6      | <b>SP000011507</b><br>Q62705K 259 |                    | TO92    |                   |                  |          |         |

\*) **SP...** = new ordering code, refer to Info Note 029/05 'Introduction of SAP and i2 for Order Management'

|                |                  |
|----------------|------------------|
| Last order:    | 31. January 2007 |
| Last delivery: | 31. July 2007    |

# PRODUCT DISCONTINUATION

## PD\_074\_06

Reason: Manufacturing at Munich Perlach will be phased out.

| DISCONTINUED |                                   |                    |         | NEW (REPLACEMENT) |                  |          |         |
|--------------|-----------------------------------|--------------------|---------|-------------------|------------------|----------|---------|
| Device       | Ordering Code *)                  | Function           | Package | Device            | Ordering Code *) | Function | Package |
| KTY21-7      | <b>SP000011508</b><br>Q62705K 260 | Temperature Sensor | TO92    | none              |                  |          |         |
| KT110        | <b>SP000011499</b><br>Q62705K 332 |                    | TO92    |                   |                  |          |         |
| KTY11-5      | <b>SP000011496</b><br>Q62705K 245 |                    | TO92    |                   |                  |          |         |
| KTY11-6      | <b>SP000011497</b><br>Q62705K 246 |                    | TO92    |                   |                  |          |         |
| KTY11-7      | <b>SP000011498</b><br>Q62705K 247 |                    | TO92    |                   |                  |          |         |

\*) **SP...** = new ordering code, refer to Info Note 029/05 'Introduction of SAP and i2 for Order Management'

|                |                  |
|----------------|------------------|
| Last order:    | 31. January 2007 |
| Last delivery: | 31. July 2007    |