

PRODUCT DISCONTINUATION



PD_017_07

Reason: Manufacturing at Munich Perlach will be phased out

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
KTY13-5	SP000013612	Temperature Sensor	PG-SOT23	KTY13-6	SP000013613	Temperature Sensor	PG-SOT23
KTY13-7	SP000013614						
KTY13-6 E6755	SP000011500						

Last order:	31. August 2007
Last delivery:	28. February 2008