

PD_043_08

Reason: Product obsolescence

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
TLE4307D V33 TLE4307D V33	SP000012829 SP000362380	Power Charge Pump and	PG-TO252-5 PG-TO252-5	no replacement			
TLE4307D V38 TLE4307D V38	SP000012828 SP000362382	Low Drop Voltage Regulator	P-TO252-5 PG-TO252-5		ποτεριασειπειτα		

Last order:	30. November 2008
Last delivery:	31. May 2009