



# PRODUCT DISCONTINUATION

PD\_096\_09

**!! UPDATE !!**

Reason:

Low customer demand

Original:

Product Discontinuation PD\_096\_09 dated 2009-06-08

**Update:**

**TUA 6036 T: Extended last order and last delivery date**

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TUA 6036 T	SP000014627	PG-TSSOP-38	Single Conv. 3-Band	TUA 6034 T	SP000013610	PG-TSSOP-38	Single Conv. 3-Band

■ Last order:	<del>2009-12-31</del>	<b>2010-12-31</b>
■ Last delivery:	<del>2010-06-30</del>	<b>2011-06-30</b>

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TUA 6030	SP000012954	PG-TSSOP-38	Single Conv. 3-Band	TUA 6034 T	SP000013610	PG-TSSOP-38	Single Conv. 3-Band

■ Last order:	2009-12-31
■ Last delivery:	2010-06-30

**Disclaimer:** The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!