

PRODUCT DISCONTINUATION



PD_107_09

Reason: Discontinuation of leaded leadfinish products. Replacement by leadfree (Green) products

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TLE6214L	SP000014123	P-DSO-12	2Ch.LowSide Switch	TLE8102SG	SP000308142	PG-DSO-12	2Ch. Low Side Switch
TLE6214L MELCO	SP000014122	P-DSO-12	2Ch.LowSide Switch	TLE8102SG	SP000377621	PG-DSO-12	2Ch. Low Side Switch
TLE6214L	SP000358261	PG-DSO-12	2Ch.LowSide Switch	TLE8102SG	SP000377621	PG-DSO-12	2Ch. Low Side Switch

■ Last order:	2010-03-31
■ Last delivery:	2010-08-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!