## PRODUCT DISCONTINUATION



PD\_127\_09

Reason: Technology Phase-out

| DISCONTINUED  |               |               |            | NEW (REPLACEMENT) |               |         |          |
|---------------|---------------|---------------|------------|-------------------|---------------|---------|----------|
| Device        | Ordering Code | Package       | Function   | Device            | Ordering Code | Package | Function |
| PBL38621/2QNA | SP000017951   | P-/PG-LCC-28  | FlexiSLIC1 |                   |               |         |          |
| PBL38621/2SHA | SP000007871   | P-/PG-SSOP-24 | FlexiSLIC1 | none              |               |         |          |
| PBL38621/2SHA | SP000233818   | P-SSOP-24     | FlexiSLIC1 |                   |               |         |          |
| PBL38621/2SOA | SP000016951   | P-/PG-DSO-24  | FlexiSLIC1 |                   |               |         |          |
| PBL38640/2QNA | SP000017953   | P-/PG-LCC-28  | FlexiSLIC1 |                   |               |         |          |
| PBL38640/2SOA | SP000016952   | P-/PG-DSO-24  | FlexiSLIC1 |                   |               |         |          |

| Last order:    | 2010-03-31 |
|----------------|------------|
| Last delivery: | 2010-09-30 |

**Disclaimer**: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

2009-09-15 Page 1 of 1