

PRODUCT DISCONTINUATION



PD_139_09

Reason: Discontinuation of leaded leadfinish products. Possible replacement by similar leadfree (Green) products

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TLE6215G	SP000013649	P-DSO24	2Ch.LowSide Switch	TLE8102SG	SP000308142	PG-DSO12	2Ch. Low Side Switch
TLE6216G	SP000013652	P-DSO20	2Ch.LowSide Switch	TLE8102SG	SP000377621	PG-DSO12	2Ch. Low Side Switch

■ Last order:	2010-10-31
■ Last delivery:	2011-04-30

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!