

PRODUCT DISCONTINUATION



PD_152_09

Reason: End of Life

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|----------------------|---------------|------------|----------|---------------------|---------------|-----------|----------|
| Device | Ordering Code | Package | Function | Device | Ordering Code | Package | Function |
| PTFA041501GL V1 | SP000532706 | PG-63248-2 | | PTFA041501E V4 | SP000737282 | H-36248-2 | |
| PTFA041501GL V1 R250 | SP000532708 | PG-63248-2 | | PTFA041501E V4 R250 | SP000749242 | H-36248-2 | |
| PTFA041501HL V1 | SP000559358 | PG-64248-2 | | PTFA041501F V4 | SP000737284 | H-37248-2 | |
| PTFA041501HL V1 R250 | SP000559360 | PG-64248-2 | | PTFA041501F V4 R250 | SP000749244 | H-37248-2 | |
| PTFA041501HL V1 S250 | SP000559362 | PG-64248-2 | | PTFA041501E V4 S250 | SP000749246 | H-37248-2 | |
| PTFA091201GL V1 | SP000229298 | PG-63248-2 | | PTFA091201E V4 | SP000317908 | H-36248-2 | |
| PTFA091201GL V1 R250 | SP000465360 | PG-63248-2 | | PTFA091201E V4 R250 | SP000387060 | H-36248-2 | |
| PTFA091201HL V1 | SP000384432 | PG-64248-2 | | PTFA091201F V4 | SP000317909 | H-37248-2 | |
| PTFA091201HL V1 R250 | SP000465362 | PG-64248-2 | | PTFA091201F V4 R250 | SP000387077 | H-37248-2 | |
| PTFA181001GL V1 | SP000229299 | PG-63248-2 | | PTFA181001E V4 | SP000376066 | H-36248-2 | |
| PTFA181001GL V1 R250 | SP000465356 | PG-63248-2 | | PTFA181001E V4 R250 | SP000393322 | H-36248-2 | |

| | |
|------------------|------------|
| ■ Last order: | 2010-05-31 |
| ■ Last delivery: | 2010-11-30 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!