

PRODUCT DISCONTINUATION



PD_045_13

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
TLE4267	SP000306738	TLE4267AKSA1	PG-TO220-7			None	
TLE4267S	SP000306741	TLE4267SAKSA1	PG-TO220-7			None	
TLE4274 V10	SP000357835	TLE4274V10AKSA1	PG-TO220-3			None	
TLE4274 V50 DENSO	SP000223139	TLE4274V50DENSONKSA1	P-TO220-3			None	
TLE4274 V85	SP000011810	TLE4274V85NKSA1	P-TO220-3			None	
TLE4274 V85	SP000361644	TLE4274V85AKSA1	PG-TO220-3			None	
TLE4274-2G V50	SP000362345	TLE42742GV50ATMA1	PG-TO263-3			None	
TLE4274G V50 DENSO	SP000223137	TLE4274GV50DENSONTMA1	P-TO263-3			None	
TLE4274G V85-2	SP000362363	TLE4274GV852ATMA1	PG-TO263-3			None	
TLE4275S	SP000306748	TLE4275SAKSA1	PG-TO220-5			None	

■ Last order:	2013-11-30
■ Last delivery:	2014-07-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!