



Product Discontinuation

PD_092_05

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code *)	Function	Package	Device	Ordering Code *)	Function	Package
TDA 5204	SP000013122 Q67037-A1169	ASK Single Conversion Receiver, 390 MHz	P-TSSOP 28	none			

*) SP... = new ordering code, refer to Info Note 029/05 'Introduction of SAP and i2 for Order Management'

Last order:	30. April 2006
Last delivery:	31. October 2006

Reason: Low demand, frequency band jammed by other services.