

PRODUCT DISCONTINUATION



PD_119_06

Reason: Phase-out of production processes

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
TDA21107	SP000015138	Single Gate Driver	P-DSO-8-12	none			
TDA21201-B7 TDA21201-P7 TDA21201-S7	SP000013685 SP000014081 SP000014082	Integrated Switch	P-TO220-7-128 P/PG-TO220-7-230 P/PG-TO220-7-3				

Last order:	30. June 2007
Last delivery:	31. December 2007