## PRODUCT DISCONTINUATION



PD\_014\_07 !! 2<sup>nd</sup> UPDATE !!

Reason: end of life product

Original: Product Discontinuation PD\_014\_07 dated 06. February 2007

Update (2007-03-08): BTS7750GP: Replacement product available

2<sup>nd</sup> Update: BTS7750GP: New replacement product and extended last order and last delivery date

DISCONTINUED			NEW (REPLACEMENT)				
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
BTS7750GP	SP000012780	TrilithIC power bridge	P-10263-15		not yet available planned for Q4/2007	bridge Novalith IC power	PG-TO263-15 PG-TO263-7

Last order:	31. August 2007	31. December 2007
Last delivery:	28. February 2008	30. June 2008

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
ITS7740G **)	SP000228893	TrilithIC power bridge	PG-DSO28-22		RoHS compliant part not yet available planned for Q4/2007	TrilithIC power bridge	PG-DSO28-22

<sup>\*\*)</sup> device was announced, but will not be transferred into volume production

Last order:	no orders and
Last delivery:	deliveries possible

2007-10-08 Page 1 of 1