

PRODUCT DISCONTINUATION



PD_028_08

Reason: low customer demand

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
SPU08P06P	SP000012086	P-Channel MOSFET	TO251-3 / IPAK	no replacement			
SPU09P06PL	SP000012876						
SPU18P06P	SP000012303						
SPU30P06P	SP000012844						

Last order:	31. October 2008
Last delivery:	30. April 2009