PRODUCT DISCONTINUATION



PD_097_09

Reason: low demand

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
PEB 3332 HT V2.1 PE	SP000098554 SP000397146	PG-TQFP-100	VINETIC-2CPE	PEB 3332 HT V2.2	SP000236903	PG-TQFP-100	VINETIC-2CPE
PEB 3341 F V2.1	SP000201606	PG-TQFP-64	VINETIC-1ATA	PEB 3341 F V2.2	SP000236907	PG-TQFP-64	VINETIC-1ATA
PEB 3352 HT V2.1	SP000222289	PG-TQFP-100	VINETIC-2AMR	none			

Last order:	2009-12-31
Last delivery:	2010-06-30

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

2009-06-29 Page 1 of 1