

PRODUCT DISCONTINUATION



PD_161_09

Reason: Discontinuation of ceramic capacitors X7R type from Infineon supplier Epcos

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TLE4982C	SP000269351	PG-SSO-3-9	Camshaft IC	TLE4984C-HT E6747 TLE4983C-HT E6547	SP000374268 SP000614788	PG-SSO-3-9 PG-SSO-3-92	Camshaft IC
TLE4925C	SP000269339	PG-SSO-3-9	Crankshaft IC	TLE4925C	SP000740928	PG-SSO-3-9	Crankshaft IC
TLE4925C-N	SP000269343	PG-SSO-3-91	Crankshaft IC	TLE4925C-N	SP000740932	PG-SSO-3-91	Crankshaft IC
TLE4926C-HTN E6747	SP000269347	PG-SSO-3-91	Crankshaft IC	TLE4926C-HTN E6547 TLE4926C-HTN E6747	SP000718262 SP000763374	PG-SSO-3-93 PG-SSO-3-91	Crankshaft IC
TLE4926C-HT E6747	SP000269345	PG-SSO-3-9	Crankshaft IC	TLE4926C-HT E6547 TLE4926C-HT E6747	SP000718258 SP000763370	PG-SSO-3-92 PG-SSO-3-9	Crankshaft IC
TLE4928C	SP000269349	PG-SSO-3-9	Transmission IC	TLE4928C E6547 TLE4928C	SP000718274 SP000763968	PG-SSO-3-92 PG-SSO-3-9	Transmission IC

■ Last order:	2010-06-30
■ Last delivery:	2011-02-28

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!