

PRODUCT DISCONTINUATION



PD_019_11

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
DTA 2006	SP000250965	PG-VQFN-48	MOPLL IC	None			
SEMPT082	SP000486212	PG-VQFN-48	MOPLL IC	None			
SEMPT082	SP000534626	PG-VQFN-48	MOPLL IC	None			
TDA 6170X	SP000011740	P-DSO-28	Satellite Sound IF IC	None			
TDA 6192 T	SP000013411	P-TSSOP-16	IF IC	None			
TDA 6192 T DRYPACK	SP000013410	PG-TSSOP-16	IF IC	None			
TMM 2000	SP000013123	P/PG-TSSOP-28	MOPLL IC	None			
TUA 1030	SP000013617	P-TSSOP-24	MOPLL IC	None			
TUA 6020	SP000012798	P/PGG-TSSOP-28	MOPLL IC	None			
TUA 6030 PHILIPS	SP000012955	P/PG-TSSOP-38	MOPLL IC	None			
TUA 6034 T	SP000013610	P/PG-TSSOP-38	MOPLL IC	None			

■ Last order:	2011-09-30
■ Last delivery:	2012-03-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

PRODUCT DISCONTINUATION



PD_019_11

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TUA 6034 T	SP000013611	P/PG-TSSOP-38	MOPLL IC	None			
TUA 6037F	SP000315896	PG-VQFN-48	MOPLL IC	None			
TUA 6039	SP000259230	PG-VQFN-48	MOPLL IC	None			
TUA 6039-2	SP000279216	PG-VQFN-48	MOPLL IC	None			
TUA 6039-2	SP000429720	PG-VQFN-48	MOPLL IC	None			
TUA 6039F-2	SP000315897	PG-VQFN-48	MOPLL IC	None			
TUA 6039F-2	SP000429724	PG-VQFN-48	MOPLL IC	None			
TUA 6041-2	SP000250163	PG-VQFN-48	MOPLL IC	None			
TUA 6041-2 HT	SP000270494	PG-VQFN-48	MOPLL IC	None			
TUA 6045	SP000018086	PG-VQFN-48	MOPLL IC	None			
TUA 6045	SP000250166	PG-VQFN-48	MOPLL IC	None			
TUA 6045-2	SP000250164	PG-VQFN-48	MOPLL IC	None			

■ Last order:	2011-09-30
■ Last delivery:	2012-03-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

PRODUCT DISCONTINUATION



PD_019_11

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TUA 6130	SP000013895	P/PG-VQFN-40	MOPLL IC	None			
TUA 8010	SP000390363	PG-VQFN-48	Silicon Tuner IC	None			
TUA 9001	SP000365064	PG-WFSGA-65	Silicon Tuner IC	None			
TUN2010	SP000012812	P/PG-TSSOP-38	MOPLL IC	None			
TUS 9090	SP000294473	PG-WF2SGA-144	RF/BB SoC	None			
KTS 6027 EVABOARD	SP000403940	n/a	MOPLL	None			
KTS 6027-2 REF TUNER	SP000641640	PG-TSSOP-28-1	MOPLL	None			
KTS 6027-2 REF TUNER	SP000015143	n/a	MOPLL	None			
SEMPT082 EVABOARD	SP000550702	n/a	MOPLL	None			
TDA 6192T EVABOARD	SP000403944	n/a	IF Amplifier	None			
TUA 6020 B4-G	SP000430134	PG-TSSOP-28-1	MOPLL	None			
TUA 6020 C4-G	SP000430138	PG-TSSOP-28-1	MOPLL	None			

■ Last order:	2011-09-30
■ Last delivery:	2012-03-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

PRODUCT DISCONTINUATION



PD_019_11

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TUA 6020 EVABOARD	SP000403948	n/a	MOPLL	None			
TUA 6030 EVABOARD	SP000403952	n/a	MOPLL	None			
TUA 6034 DVB-T REF NIM	SP000403956	n/a	MOPLL	None			
TUA 6034 EVABOARD	SP000403960	n/a	MOPLL	None			
TUA 6034 REF TUNER	SP000013609	n/a	MOPLL	None			
TUA 6034T ATSC EVABOARD	SP000403968	n/a	MOPLL	None			
TUA 6034T ISDB-T EVABOAR	SP000403980	n/a	MOPLL	None			
TUA 6034T ISDB-T REFT	SP000431860	PG-TSSOP-38-2	MOPLL	None			
TUA 6034T TDA6192V M H N	SP000403964	n/a	MOPLL	None			
TUA 6034V EVABOARD	SP000403984	n/a	MOPLL	None			
TUA 6035 T	SP000709440	PG-TSSOP-38-2	MOPLL	None			
TUA 6035 V	SP000709444	PG-VQFN-48-4	MOPLL	None			

■ Last order:	2011-09-30
■ Last delivery:	2012-03-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

PRODUCT DISCONTINUATION



PD_019_11

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TUA 6036 EVABOARD	SP000403996	n/a	MOPLL	None			
TUA 6037 B2 20UM	SP000429700	PG-VQFN-48-48	MOPLL	None			
TUA 6037 B2 25 UM	SP000429704	PG-VQFN-48-48	MOPLL	None			
TUA 6037 EVABOARD	SP000404000	n/a	MOPLL	None			
TUA 6037F 20UM	SP000429712	PG-VQFN-48-48	MOPLL	None			
TUA 6037F 25UM	SP000429716	PG-VQFN-48-48	MOPLL	None			
TUA 6037F EVABOARD	SP000404004	n/a	MOPLL	None			
TUA 6039 EVABOARD	SP000404008	n/a	MOPLL	None			
TUA 6039 HALF NIM DVB-T	SP000404012	n/a	MOPLL	None			
TUA 6039-2 EVABOARD	SP000429614	n/a	MOPLL	None			
TUA 6039-B2	SP000279277	PG-VQFN-48-48	MOPLL	None			
TUA 6039F-2 DVB-T H H N	SP000403988	n/a	MOPLL	None			

■ Last order:	2011-09-30
■ Last delivery:	2012-03-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

PRODUCT DISCONTINUATION



PD_019_11

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TUA 6039F-2 EVABOARD	SP000404016	n/a	MOPLL	None			
TUA 6039F-2 M H N ATSC	SP000403992	n/a	MOPLL	None			
TUA 6039F-2 M H N DVB-T	SP000404108	n/a	MOPLL	None			
TUA 6041 HALF NIM 3 BAND	SP000404144	n/a	MOPLL	None			
TUA 6041 HALF NIM DVB-T	SP000404020	n/a	MOPLL	None			
TUA 6041 HALF NIM UHF	SP000404140	n/a	MOPLL	None			
TUA 6041-2 B3 20UM	SP000410438	PG-VQFN-48-22	MOPLL	None			
TUA 6041-2 B3 25UM	SP000429728	PG-VQFN-48-48	MOPLL	None			
TUA 6041-2 EVABOARD	SP000404024	n/a	MOPLL	None			
TUA 6041-2HT EVABOARD	SP000404028	n/a	MOPLL	None			
TUA 6045 A2	SP000404156	PG-VQFN-48-4	MOPLL	None			
TUA 6045 B2	SP000404160	PG-VQFN-48-4	MOPLL	None			

■ Last order:	2011-09-30
■ Last delivery:	2012-03-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

PRODUCT DISCONTINUATION



PD_019_11

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TUA 6045 B22	SP000404164	PG-VQFN-48-4	MOPLL	None			
TUA 6045 HALF NIM DVB-T	SP000404032	n/a	MOPLL	None			
TUA 6045 REF TUNER	SP000404168	PG-VQFN-48-4	MOPLL	None			
TUA 6045-2 B3 20UM	SP000410448	PG-VQFN-48-48	MOPLL	None			
TUA 6045-2 B3 25UM	SP000429732	PG-VQFN-48-48	MOPLL	None			
TUA 6045-2 EVABOA ISDB-T	SP000404148	n/a	MOPLL	None			
TUA 6045-2 EVABOAR ATSC	SP000404152	n/a	MOPLL	None			
TUA 6045-2 EVABOAR DVB-T	SP000404038	n/a	MOPLL	None			
TUA 8010 BASE BOARD	SP000460456	n/a	Silicon Tuner	None			
TUA 8010 RF DAUGHTER EXT	SP000460396	n/a	Silicon Tuner	None			
TUA 8010 RF DAUGHTER INT	SP000459884	n/a	Silicon Tuner	None			
TUA 9000	SP000251083	PG-WFSGA-65-1	Silicon Tuner	None			

■ Last order:	2011-09-30
■ Last delivery:	2012-03-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

PRODUCT DISCONTINUATION



PD_019_11

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TUA 9000 BASE BOARD	SP000402662	n/a	Silicon Tuner	None			
TUA 9000 RF DAUGHTER	SP000402658	n/a	Silicon Tuner	None			
TUA 9001 + AF9035 JOINTB	SP000408264	n/a	Silicon Tuner	None			
TUA 9001 AF9035 N DONG	SP000455838	n/a	Silicon Tuner	None			
TUA 9001 BARE DIE	SP000634194	PG-WFSGA-65-2	Silicon Tuner	None			
TUA 9001 BASE BOARD	SP000402654	n/a	Silicon Tuner	None			
TUA 9001 CXD1968 SONY N	SP000403624	n/a	Silicon Tuner	None			
TUA 9001 EVA KIT	SP000478738	n/a	Silicon Tuner	None			
TUA 9001 RF DAUGHTER	SP000402650	n/a	Silicon Tuner	None			
TUA 9001 WAFER	SP000492148	PG-WFSGA-65-2	Silicon Tuner	None			
TUA 9001+AF9033 SDIO TS	SP000465082	n/a	Silicon Tuner	None			
TUA6120 C1 EVABOARD	SP000013166	n/a	Satellite Tuner	None			

■ Last order:	2011-09-30
■ Last delivery:	2012-03-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

PRODUCT DISCONTINUATION



PD_019_11

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Package	Function	Device	Ordering Code	Package	Function
TUS 9090 BASE BOARD	SP000465116	n/a	RF/BB SoC	None			
TUS 9090 RDK1.0 DEBUG	SP000402638	n/a	RF/BB SoC	None			
TUS 9090 RDK1.0 RF PERFO	SP000402642	n/a	RF/BB SoC	None			
TUS 9090 RDK1.0 SOCKET	SP000402646	n/a	RF/BB SoC	None			
TUS 9090 RDK2.0 RF PERFO	SP000440302	n/a	RF/BB SoC	None			
TUS 9090 RDK2.0 SDIO C	SP000440314	n/a	RF/BB SoC	None			
TUS 9090 RDK2.0 SOCKET	SP000440308	n/a	RF/BB SoC	None			

■ Last order:	2011-09-30
■ Last delivery:	2012-03-31

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!